

## Department of Transport

## Repair Design Approval

This approval is issued to: Number: O-RAP99-097

Toronto Sky Aviation Inc. Issue No.: 5

30 Rayette Rd. Approval Date: July 15, 1999

Concord, Ontario Issue Date: November 24, 2015

Canada L4K 2G3

Responsible Office: Ontario

Aircraft/Engine Type or Model: Appliance MOD/REPAIR

Registration/Serial No.:

Canadian Type Certificate or Equivalent: (Appliance MOD/REPAIR)

Description of Type Design Change: Multiple Repairs to Aircraft Component / Appliance Items

Installation/Operating Data,

Required Equipment and Limitations:

Repairs must be performed in accordance with Component Rewind Manuals (CRM) identified in Toronto Sky Aviation Inc. (TSA) Eligibility Listings No. TSA-011, dated 14 July 1999, or later Transport Canada approved revisions.

Final assembly testing and installation of the repaired components must be performed in accordance with the existing OEM maintenance instructions.

-- END --



Conditions: This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this repair, the installer shall establish that the interrelationship between this repair and any other modification(s) incorporated will not adversely affect the airworthiness of the modified product.

> Zoskales Teclemariam For Minister of Transport

